



Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

DOGM  
MINERALS PROGRAM  
FILE COPY

September 13, 1989

TO: Minerals File

FROM: D. Wayne Hedberg, Reclamation Hydrologist *DWH*

RE: Field Inspection, Aggra-Insulite Corporation, MM Claims, S/041/013, Sevier County, Utah

On September 13, 1989, Wayne Hedberg inspected this small mining operation. No activity was evident at the time of my inspection, although it was apparent that there has been recent activity at the mine site. Onsite surface disturbance was visually estimated at -2 1/2 acres, not including the access road.

Access the mine site by exiting Interstate 70 at the Sevier, Utah exit junction with Highway 89 and Highway 4. Highway 4 is the access road to the Fremont Indian State Park Museum. Take Highway 4 from the junction with route 89 and I-70 and head southwest, approximately 1.4 miles to a dirt road turnoff on the right hand shoulder of the road. Follow this dirt road another 6/10ths of a mile due west to the mine site.

Onsite mining equipment consisted of the following: 1 - Allis-Chalmers front end loader, 1 - Worthington diesel air compressor, 1 - old D-3 Caterpillar dozer, 1 - old Mac truck and trailer, a spare engine assumed to be for the air compressor, 3 - small electric motors, a primary and secondary crushing and screening unit with associated conveyors feeding three small stockpiles. The stockpiles of crushed ore varied from 3/4 inch minus to sand-sized material. There was assorted extraneous pieces of scrap metal and spare mining equipment parts scattered on the site as well.

On top of the highwall was a small Gardner/Denver portable airtrack drilling unit that was being used to drill and blast the face of the highwall down to the base of the small quarry. A significant amount of rubbleized ore had been recently shot down from the face of the outcrop. This was being used as feed stock to the primary and secondary crushing unit. No significant environmental or public health and safety concerns were noted during the inspection. Several pictures of the mine site were taken for the file.

jb  
cc: Kelly Parks, Aggra-Insulite  
Lowell Braxton  
MN2/60